South Dakota Department of Health (X3) DATE SURVEY (X2) MULTIPLE CONSTRUCTION STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA COMPLETED AND PLAN OF CORRECTION IDENTIFICATION NUMBER: A. BUILDING: _ B. WING 10/19/2023 11048 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER **515 OHIO STREET** PARKVIEW APARTMENTS ASSISTED LIVING WAKONDA, SD 57073 PROVIDER'S PLAN OF CORRECTION (X5) SUMMARY STATEMENT OF DEFICIENCIES (X4) ID COMPLETE (EACH CORRECTIVE ACTION SHOULD BE (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX PREFIX DATE CROSS-REFERENCED TO THE APPROPRIATE REGULATORY OR LSC IDENTIFYING INFORMATION) TAG TAG DEFICIENCY) S 000 S 000 Compliance Statement A licensure survey for compliance with the Administrative Rules of South Dakota, Article 44:70, Assisted Living Centers, requirements for assisted living centers, was conducted from 10/17/23 through 10/19/23. Parkview Apartments Assisted Living was found in compliance.

Color Color

TITLE Administrator (X6) DATE

11/03/2023

STATE FORM

NOV 03 2023

SD DOH-OLC

If continuation sheet 1 of 1